



ATV/UTV T-MAP SENSORS

CODE B | KEYWORD 4

CAPTEURS T-MAP POUR VTT/SSV

Brand new Quad Logic T-map sensor for almost every Polaris EFI model. A dirty or bad T-map can cause rough or inconsistent idle, stalling, or just overall poor performance. Replace it now with this unit from Quad Logic.

**65-20001**

OEM# 707000995, 420874650, 707000564



Photo For
Reference
Only

65-40001

OEM# 2410422, 2411528

CC	Model	Year	Part No.
Can-Am™			
ATV			
400	OUTLANDER 400	2008-2014	65-20001
450	OUTLANDER 450	2015-2020	65-20001
500	OUTLANDER 500	2007-2015	65-20001
500	RENEGADE 500	2008-2015	65-20001
570	OUTLANDER 570	2016-2021	65-20001
570	RENEGADE 570	2016-2021	65-20001
650	OUTLANDER 650	2006-2019	65-20001
650	RENEGADE 650	2018-2019	65-20001
800	OUTLANDER 800	2006-2015	65-20001
800	RENEGADE 800	2007-2015	65-20001
850	OUTLANDER 850	2016-2021	65-20001
850	RENEGADE 850	2016-2021	65-20001
1000	OUTLANDER 1000	2012-2021	65-20001
1000	RENEGADE 1000	2012-2021	65-20001
UTV/SXS			
425	DEFENDER 425 HD5	2017-2021	65-20001
800	COMMANDER 800	2011-2020	65-20001
800	DEFENDER 800 HD8	2016-2019	65-20001
800	MAVERICK TRAIL 800	2018-2020	65-20001
1000	COMMANDER 1000	2011-2020	65-20001
1000	DEFENDER 1000 HD10	2016-2019	65-20001
1000	MAVERICK 1000 (ALL)	2013-2021	65-20001
Polaris™			
ATV			
325	HAWKEYE 325	2015	65-40001
325	SPORTSMAN 325 ETX	2015	65-40001
450	SPORTSMAN 450	2016-2021	65-40001

CC	Model	Year	Part No.
Polaris™			
ATV			
570	SPORTSMAN 570	2014-2021	65-40001
700	SPORTSMAN 700 EFI	2004-2008	65-40001
800	SPORTSMAN 800	2005-2014	65-40001
850	SCRAMBLER 850	2013-2021	65-40001
850	SPORTSMAN 850	2012-2021	65-40001
1000	SCRAMBLER 1000	2014-2021	65-40001
1000	SPORTSMAN 1000	2015-2021	65-40001
UTV/SXS			
150	ACE 150	2017-2021	65-40001
150	RANGER 150	2018-2021	65-40001
325	ACE 325	2014-2016	65-40001
325	RANGER 325 ETX	2015-2016	65-40001
500	ACE 500	2017-2019	65-40001
500	RANGER 500	2017-2021	65-40001
570	RANGER 570	2014-2021	65-40001
570	RZR 570 (Only models w/4 position keyswitch)	2012-2018	65-40001
700	RANGER 700	2005-2009	65-40001
800	RZR 800	2008-2014	65-40001
900	ACE 900	2016-2019	65-40001
900	RANGER 900 XP	2013-2019	65-40001
900	RANGER XP 900	2013-2019	65-40001
900	RZR 900 (ALL)	2015-2020	65-40001
1000	GENERAL 1000	2016-2021	65-40001
1000	RANGER XP 1000	2017-2018	65-40001
1000	RZR 1000 (ALL)	2014-2021	65-40001
1000	RZR RS1 1000	2018-2021	65-40001
1000	RZR TURBO (all except PRO-XP)	2016-2021	65-40001

ATV HANDLEBAR SWITCH BLOCK

BLOC DE COMMUTATEUR DE GUIDON POUR VTT

If one of your controls quit working it is probably the internal switch on the handlebar block. Fix it with this cost effective exact replacement! This complete block has all the same switches including hi/lo/off beam, off/run/off, and reverse override. Simple installation.



Part No. 33-41201
Code B
Keyword 4

CC	Model	Year
Polaris™		
ATV		
325	MAGNUM 325	2002
330	MAGNUM 330	2003-2006
400	HAWKEYE 400	2011-2014
400	SPORTSMAN 400	2002-2004
400	SPORTSMAN 400 HO	2008-2014
400	XPLOER 400	2002
450	SPORTSMAN 450	2006-2007
450	SPORTSMAN 450 HO	2016-2021
500	ATP 500	2004-2005
500	MAGNUM 500	2002
500	SCRAMBLER 500	2002-2009

CC	Model	Year
Polaris™		
ATV		
500	SPORTSMAN 500	2002-2013
550	SPORTSMAN 550	2009-2014
570	SPORTSMAN 570	2014-2021
600	SPORTSMAN 600	2003
700	SPORTSMAN 700	2002-2007
800	SPORTSMAN 800	2005-2014
850	SCRAMBLER 850	2013-2021
850	SPORTSMAN 850	2009-2021
1000	SCRAMBLER 1000	2014-2021
1000	SPORTSMAN 1000	2015-2021