


NEW SPX PRODUCTS / NOUVEAUX PRODUITS


STATOR ASSEMBLY AND PICK-UP COIL / STATORS ET BOBINES DE DÉTECTION

NEW

KEYWORD 16



- 892-0016**
- 7 Wires / 1 connector / 5 terminal. 10+2 Coil
 - Wire L:15/22.5 /25cm



- 892-0106**
- Hole 6.4mm, C To C 31.8-35mm
 - Wire L:20cm

Part No.	Code	List Price
892-0016	B	209.95
892-0106	B	19.95

Model	Years	Stator	Pick Up Coil
Lynx™			
5900 FCE	2001-2002	892-0016	892-0106
6900 FCE	1999-2003	892-0016	892-0106
FOREST 440	1999	892-0016	892-0106
GLX 5900 FCE	1999-2000	892-0016	892-0106
RANGER KING 500	1999	892-0016	892-0106
SPORT XR 500	1999	892-0016	892-0106
Ski-Doo™			
FORMULA DELUXE 380/500	2000	892-0016	892-0106
FORMULA S	1996-2000	892-0016	892-0106
FORMULA SL	1996-1999	892-0016	892-0106
MXZ 440	1997-2000	892-0016	892-0106
SKANDIC 380	1996-1998	892-0016	892-0106

Model	Years	Stator	Pick Up Coil
Ski-Doo™			
SKANDIC 500	1996-1998	892-0016	892-0106
SKANDIC 500F	2001-2002	892-0016	892-0106
SKANDIC 600	2001-2003	892-0016	892-0106
SKANDIC SUPER WIDE TRACK 500 F	2003	892-0016	892-0106
SKANDIC SWT	1997-2000	892-0016	892-0106
SKANDIC WIDE TRACK 500 F	2003	892-0016	892-0106
SKANDIC WT	1996-2000	892-0016	892-0106
SKANDIC WT LC	1997-2000	892-0016	892-0106
TOURING E	1996-1998	892-0016	892-0106
TOURING E LT	1996-1997	892-0016	892-0106
TOURING LE	1996-1998	892-0016	892-0106
TOURING SLE	1996-1998	892-0016	892-0106

PART NO. 854-1020 HAS BEEN DISCONTINUED REMOVED FROM ONLINE CATALOGUE ONLY